

## **Refit 2018 up to now**

### **Hull**

Gelshield treatment  
New epoxy foam inside rudder  
Hull and deck new paint

### **Kitchen**

Gas stove + oven (ENO - Origin gas oven)

**Heads:** New head

### **Electronics**

Raymarine EV100 Autopilot  
Raymarine Chart plotter (Element 7S)  
Raymarine (tridata i70, wind, speed and depth)  
VHF (ICOM - IC-M330GE)  
AIS (Amec - CAMINO-108S AIS Transponder)  
Compass on both sides

### **Electricity**

LED navigation lights, stern light, mooring light and steaming light  
LED interior lighting  
Service battery (VartaAGM 260Ah)  
Battery charger (DOMECTIC PerfectCharge MCA1235)  
Solar Panel (70W)  
Solar Panel controller Victron MPTT  
All wiring replaced

### **Mooring**

Rocna 15kg anchor, 25m 8mm chain + 45m line 14mm  
15kg delta anchor chain + line

### **Equipment**

Honda 2.3 PS outboard engine  
Bombard AX2 dinghy  
Diesel Heating (AUTOTERM AIR diesel air heater 44D)

### **Rigging**

Dyform Standing rigging (2019)  
Foresail furler Selden (2019)  
All running rigging replaced (2019)  
Boom vang from Selden (2019)

### **Sails**

Elvström sails Hydranet  
Mainsail (2019)  
Genua (2019)  
Fock (2019)  
Stormsail 9m<sup>2</sup> (2019)  
1 light symmetrical spinnaker (from previous owner)  
1 heavy symmetrical spinnaker (from previous owner)  
1 blooper sail (from previous owner)

**Security**

1 Epirb (ACR EPIRB "GlobalFIX V4")  
1 Manual bilge pump  
Electrical bilge pump (not plugged / plumbed and wired)  
2 Life Jacket (SEATEC - Life Jacket X-PRO 300) + Safety lines  
Life line from stern to bow

**Engine**

Abgaskrümmer replaced  
All diesel hoses replaced  
Water separator diesel pre filter  
Air filter  
Engine bay sound insulation new  
Engine bay sanded and painted anew  
Rubber Shaft Seal

**General refit**

All interior wood sanded and varnished anew  
Cushions housings replaced  
Forward Cabin insulated  
Interior hull painted  
Bilge sanded and painted

**Plumbing**

Water circuit and tank replaced (flexible 100L)